

Remington Arms

I telephoned your customer service dept. Monday 5-21-84 and they advised me to send the following rifle @ 700 BOL 7mm Mag. for repairs. The rifle accidentally fired while starting to eject a cartridge out of the chamber.

Q. Why the shellfind have no idea, the only modification done to the rifle was having it glass bedded and the sights taken off all done by a reputable gunsmith. Also the face and extractor ~~area~~ of the bolt show excessive wear for a rifle that has only been shot very little (~~3004 loads~~). The rifle was bought in 1980 but has been used very little.

If the many rifles and shotguns I own, most of them are Remingtons-- which I have enjoyed for years and I am confident that this rifle will be checked and repaired if needed.

John C. Green
510 3rd Ave.
Worthington, Ky. 41185

(603) 826-2493

DEFENDANT'S EXHIBIT

