


left our factory, and not replaced, indicating the adjustments had been tampered with. In future use, we strongly advise that the trigger not be adjusted by untrained non-Remington personnel.

Since we found the firearm to function properly in every respect, we are prepared to return it in its present condition (after re-sealing the trigger assembly adjusting screws). However, if you desire, we will install a new trigger assembly at no-charge, as a gesture of good-will, if it will restore your confidence in the rifle (either option subject to a \$10.00 handling plus return shipping fee). We will await your decision and reply.

Thank you for affording us the opportunity to examine your rifle and report our findings.

Sincerely,

A handwritten signature in cursive script, appearing to read "J.A. Stekl".

J.A. Stekl, Specialist  
Product Service

JAS:tp