

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 91-25955

INITIAL <b>LCS</b>	CUSTOMER ORDER NO.		SERIAL NUMBER <b>C6250545</b>		NEW SERIAL NUMBER	MODEL AND GRADE <b>700 30-06</b>	ADL/LS
DATE RECEIVED <b>12/10/91</b>	DATE OPENED <b>12/12/91</b>	DATE CODE <b>KI 5-88</b>					
ACCESSORIES <b>W/STUDS</b>							

FROM:	SHIP TO:
GREAT GUNS INC OF TYLER TEXAS 5729 HWY 31 WEST TYLER TX 75709 USA	GREAT GUNS INC OF TYLER TEXAS 5729 HWY 31 WEST TYLER TX 75709 USA

CUST NO: 009222 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PPOM. DATE	ESTIMATED	VIA <b>UPS</b>
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

- GUN CONDITION
- NEW
  - LIGHTLY WORN
  - WORN
  - VERY WORN
  - UNREPAIRABLE

REPAIR CHARGE
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

*gun fires when bolt is closed*

MAIN FAULT *As received, rear safety cam was stuck to regulate trigger assembly housing. When bolt was inserted and closed, firing pin simply followed down on loading cam. Trigger assembly is contaminated with debris, gun may require trigger assembly not functioning properly. Trigger pin measured to be 4.75" possibly seat left - .014"*

PARTS	COMMENTS				
	<i>Offer to clean prevent trigger assembly if possible. If not possible, offer replacement generally at normal cost, as gesture of good-will.</i>				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91