

RECEIVING AND ESTIMATING REPORT

COMMENTS

*steel*

ORDER R 92-02761

INITIAL: FPS  
 CUSTOMER ORDER NO.: 3192R  
 DATE RECEIVED: 01/15/92  
 DATE OPENED: 00/00/00  
 DATE CODE: XJ 12-89

SERIAL NUMBER: C6484115  
 NEW SERIAL NUMBER:  
 MODEL AND GRADE: 700 30-06 BDL

ACCESSORIES: W/STUDS

FROM: GRICE WHOLESALE  
 216 REED ST  
 PO BOX 1028  
 CLEARFIELD PA 16830

CUST NO: 005411 WILM

SHIP TO: GRICE WHOLESALE  
 216 REED ST  
 PO BOX 1028  
 CLEARFIELD PA 16830

ACCOUNT NUMBER: PROM. DATE: ESTIMATED: VIA: UPS

GUN CONDITION:  
 NEW  
 LIGHTLY WORN  
 WORN  
 VERY WORN  
 UNREPAIRABLE

WRITE  CLEAN/TEST

REPAIR CHARGE:  
 EXCISE:  
 TAX:  
 INSURANCE:  
 UPS:  
 PARCEL POST:  
 TOTAL:

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.					E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Trigger assembly is rusted - rust on exterior of housing and on inner surfaces - internal parts are not moving freely. If properly fixed or bolt gun is rusted also. Core of barrel contains rust also. This rifle has not been properly maintained.

PARTS:

COMMENTS: Offer replacement trigger assembly at 1/2 original cost, as a gesture of good-will.  
 When rifle is returned, analyze and advise proper and routine maintenance section!!

REPAIRMAN: [Signature]	PROOF:	CLEAN:	TEST:	TARGET:	PATTERN:
GALLERY TESTER:	DATE:	DATE:	DATE:	DATE:	DATE: