

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

November 23, 1988

Gunrack, Inc.
ATTN: Mr. W.T. Reynolds
208 Midway Acres
Ripley, WV 25271

Dear Mr. Reynolds:

Examination has been completed on the Model Seven 6 mm Rem caliber rifle, serial number 7620806, that you returned to us because "while bolting up it voluntary discharges."

The returned firearm, which was produced in August of 1983, was found to bear our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the gun appeared to be good, however, it was noted that the stock had some minor scratches. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not produce any type of firing malfunction. Factory seals were intact on the trigger adjustment screws, indicating no adjustments were made to the trigger outside our factory. Trigger pull was measured to be 4 pounds, and sear lift with the safety in the "on-safe" position was well within specifications at .0115." The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.