RECEIVED

神元:519/8

J. A. STEKL

1312 Roundelay St. Bastrop, La. 71220 April 9, 1979

Remington Arms Co., Inc. Box 179 Ilion, N. Y. 13357

Att: J. A. Stekl

Dear Mr. Stekl,

Let me assure you my integrity and honesty go without question by those who know me. If I tell you in sincerity that something happened, you can safely bet large sums of money on it.

I also tried to duplicate these incidents without success. With my limited knowledge of the internal functions of a gun, I would not under any circumstances try to adjust a weight-of-pull or an overtravel adjustment, whatever or wherever they may be. I also do not stick my fingers into electric sockets to see if the electricity is on for the same reason.

I do not expect you to accept any liability in this matter. I sent the gun to you because I felt there was no one better qualified to examine it and tell me if there was anything wrong with it.

If these alleged screw tamperings might have caused these alleged firings, by all means return the gun as is. If, in your expert opinion, they did not, and you can't find and correct any other thing that might have caused these alleged firings, please send the gun back anyway and I will get rid of it post-haste.

Respectfully,

Lt. Ray Harrison, Enf. Div. Wildlife and Fisheries Comm. State of Louisiana

RH/rj