

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-24362

INITIAL

CUSTOMER ORDER NO.

LCS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/22/91

11/26/91

KI 5-88

C6251170

700 30-06

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

HILLS INC
1720 CAPITAL BLVD
RALEIGH
USA

NC 27604

SHIP TO:

HILLS INC
1720 CAPITAL BLVD
RALEIGH
USANC
27604

CUST NO: 004393 ILION L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

12-9

UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Trigger assembly rusted from unknown source - internal parts not moving fully nor properly - trigger activation not consistent nor positive. Problem could not be duplicated, but with corrosion of trigger assembly, malfunction could occur.

PARTS

COMMENTS

Replace trigger assembly at no charge, as gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATT

BWT
GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV.

PPS 02341