

RECEIVED

APR 24 1990

J.A. STEKL

Route 8 Box 26
Fort Payne, Al.
35967
April 18, 1990

Jim Stekl
Remington Arms Co., Inc.
Product Service
14 Hoefler Ave.
Ilion, NY 13357

Dear Mr. Stekl,

I have a model 700 Winchester, 300 magnum rifle. Last October my rifle went off and shot through my truck. I was standing about 25 feet from the truck, holding my rifle by the forearm in one hand. I was talking to my brother when the gun fired. My nephew was almost hit instead of the truck. I immediately checked the safety, and it was on safety. When I pushed the bolt forward to lock it down the gun fired. I knew something was broken so I took the gun to a gunsmith. He said the Trigger Connector part # 19461 had broken (Schematic # 58). The gunsmith sent the gun to Remington Arms Co and had it fixed. I just got it back April 16, 1990 because the part was restricted and he had to wait to get it. The gunsmith's name is Ronald Hughes. His telephone number is (205) 845-4145.

My wife has called the main office in Ilion, New York and was informed to send estimates for repair of the truck and the cost of the gun repair for reimbursement. I have enclosed the estimates and a receipt for the gun repair.

If you need further information please call Harold Hughes at (205) 845-7861 or write Route 8 Box 26, Fort Payne, Al. 35967

I appreciate your help regarding this matter.

Sincerely,

Harold Hughes
Route 8 Box 26
Fort Payne, Al.

Harold Hughes
4-18-90