

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/26/90	DATE OPENED 01/03/91	DATE CODE ED 10-83	SERIAL NUMBER R6492095	MODEL AND GRADE 700 270 BDL/LH	ORDER R 91-002		
ACCESSORIES W/STUDS		SCOPE BASE					

FROM:	SHIP TO:
J R 'S GUNSMITHING KEARNEY COMMERCIAL CNTR KEARNEY MO 64060	J R 'S GUNSMITHING KEARNEY COMMERCIAL CNTR KEARNEY MO 64060

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Trigger malfunctions, rifle is not safe"

MAIN FAULT
Trigger assembly has been removed outside of factory and improperly re-installed. Safety arm was lodged under gun safety cam as trigger; could not be moved. Sides of trigger housing were caved in, due to improper replacement of retaining pins, binding the cam-safety cam from movement.

PARTS		REPAIRMAN <i>[Signature]</i>				PROOF	CLEAN	TEST	TARGET	PATTERN
		GALLERY TESTER				DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 02543