

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS ATTN JIM STEKL	
CS	DATE RECEIVED 5/20/91	DATE OPENED 05/23/91	DATE CODE BU 1-71	SERIAL NUMBER 6492205	MODEL AND GRADE 700 270 ADL
ACCESSORIES	SCOPE BASE				ORDER 91-11206
L/REAR SIGHT					
FROM:			SHIP TO:		
JACKALOPE GUN SHOP 1048 SOUTH 5TH ST. DOUGLAS USA			JACKALOPE GUN SHOP 1048 SOUTH 5TH ST. DOUGLAS USA		
L			L		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C		WRITE <input type="checkbox"/>	CLEAN/TEST	FROM DATE
					ESTIMATED
					VIA UPS
PAIR CHARGE					
TAX		INSURANCE		UPS	PARCEL POST
TOTAL					
GUN CONDITION:					
<input type="checkbox"/> NEW <input type="checkbox"/> SLIGHTLY WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> MISUSED <input type="checkbox"/> MARRED					
CUSTOMER'S REQUEST					
<i>"... This rifle fires when safety is released or the bolt is closed."</i>					
IN FAULT <i>No fault found - cannot duplicate above complaints. Trigger pull 5 pounds, rear - lift .009". However, removal of action from stock revealed excessive dirt and oil on bottom of action and on trigger assembly. Rifle has not been properly maintained.</i>					
RTS <i>Offer to return rifle with present trigger assembly, after cleaning, or offer to replace trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.</i>					
REPAIRMAN		PROOF	CLEAN	TEST	TARGET
GALLERY TESTER		DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 02549