

**Remington.**



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

**ILION, NEW YORK 13357**

TELEPHONE (315) 894-9961

February 14, 1989

Mr. Leslie Johnson  
R.R. #1, Box 309  
Whealland, MO 65779

Dear Mr. Johnson:

Your letter of January 16, 1989 that was addressed to the Fire-arms Product Manager, Remington Arms Company, Inc., Bridgeport, Connecticut, advising us of the accidental firing you experienced while using your Model 700 308 Win. caliber rifle, serial number B6483050, has been forwarded to this office for response.

Generally, the type of problem you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger, when the safety was in the "fire" position.

We would very much like to have the opportunity to examine your rifle so that we can evaluate the cause of your accident. If you are willing to permit us to examine the gun at our laboratory here in Ilion, NY, we will be glad to advise you promptly of our findings.

If this is agreeable to you, please, at your convenience, return the rifle via UPS, transportation C.O.D. to:

Remington Arms Co., Inc.  
Attn: J.A. Stekl, Specialist  
Product Service  
14 Hoefler Ave  
Ilion, NY 13357

Be sure to mark the two (2) butt ends of the outside of the pack-