

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

December 20, 1989

L.B.W. Shooters Supply
416 Bridge St.
Staunton, VA 24401

Dear Sir:

Examination has been completed on the Model 700 ADL 270 Win. caliber rifle, serial number 6442537, that you returned to us a short time ago because, "Customer reports rifle sometimes goes off when bolt is closed."

The returned firearm, which was produced in May of 1971, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections before being shipped from our factory.

The general condition of the gun appeared to be well used, and it was noted that the stock has been glass-bedded after it had left our factory. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not produce any malfunctions. Repeated efforts were made to cause the rifle to fire upon bolt closing, and it did not occur. Trigger pull was measured to be 4-1/2 pounds, and the sear-lift with the safety in the "on-safe" position was within specifications at .0105". It was noted, however, that the factory sealant was missing from the weight-of-pull and overtravel adjusting screws, indicating they had been adjusted outside our factory. In addition, examination of the trigger revealed that a trigger shoe had been installed at some