

Licking Valley Armory
Oak Hill Rd, RR #4 Box 290
Falmouth, Kentucky 41040



NRA Life Member
FFL #61-33040
Bus. (606) 654-2777


1/12/94

Remington Arms Co., Inc.
Attn, Arms Service Section
14 Hoefler ave
Ilion, New York. 13357

The Remington 700 rifle was bought by my customer on August of 1993. The rifle was range tested and zeroed in, but on his hunting trip the malfunction occurred. He said that when he chambered a round the rifle discharged taking some skin off his thumb. "the firearm was on safe"! thinking that somehow he might have taken the safety off, he rechambered a round paying more attention to detail: "gun on safe" he observed that the firing pin was moving in the firing position denting the primer slightly.

The gentlemen brought the firearm in my shop for service, because he trusted my work on his firearms. I advised him that I should contact Remington service center, since the rifle is under warranty and I am not a Remington warranty station agent at this moment. Per our telephone conversation of 1/12/94, I am shipping you the Remington 700 BDL synthetic stocked rifle in .300 Wby. cal serial # C 6521903 for repair.

Yours Very Truly


Jacques H Capon
Gunsmith

DEALER IN MILITARY
Uniform, Edge Weapon
Head Gear, Accoutrements
War Relics



FFL #61-33040
Bus. (606) 654-2777
BILL, JACQUES
JEAN PAUL

LICKING VALLEY ARMORY

Oak Hill Rd., RR #4 Box 290
Falmouth, Kentucky 41040

JACQUES H. CAPON, Master Gunsmith
20 Years Experience
Stock Work, Customizing
Bluing, General Repair

NRA Life Member