

October 15, 1992

Mr. Stekl
Remington Fire Arms
14 Hoefler Ave.
Ilion, NY 13357

Mr. Stekl:

Enclosed please find the Remington Model 700 BDL 30-06 rifle,
S/N A6478653, we discussed today.

This rifle seriously malfunctioned during my recent elk hunting
trip. I had returned to our base camp and went to unload the
rifle. When I turned off the safety it immediately fired.

A friend of mine had a 7mm model 700 BDL that discharged under
the same circumstances. He has since sold his Remington and
purchased a different rifle.

I know of only one other owner of the model 700 BDL and both of
our rifles have demonstrated this defect.

As I mentioned, if the repairs and/or updates are going to exceed
the \$15.00 please return the rifle to me unrepaired and I will
sell it and purchase a more reliable rifle.

Best Regards.

Rob Liepse
133 East 5th Ave.
Longmont, Colorado 80501
(303)772-4561 Home
(303)451-1300 Work (daytime)