


Gibbes Goodwin



FFL 1-64-034-01-2M-33255

April 27, 1993

Remington Arms Company  
Arms Service Section  
14 Hoefler Avenue  
Ilion, N.Y. 13357

Attn: Dennis Sanita

Re: R93-05444

Dear Dennis:

As we discussed by phone last week, Mr. Lester has asked me to authorize you to make whatever repair/replacement of the trigger system you deem appropriate, and return the model 700 BDL as soon as possible. He withdraws his request for help on the "Blazer transmission repair."

I believe the right thing to do is expedite the replacement of the trigger assembly and return the gun as quickly as possible.

Thanks again for your assistance.

Sincerely yours,



L. Gibbes Goodwin

LGG/jg

Route 4, Box 209C • County Home Road • Ellisville, Mississippi 39437 • (601) 477-GUNS

PPS 03040