

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS <i>Stake</i>			
DATE RECEIVED 10/02/90	DATE OPENED 10/11/90	DATE CODE BV 1-79	SERIAL NUMBER A6717240	MODEL AND GRADE 700 22-250 CLASSIC		ORDER R 90-2629	
ACCESSORIES W/STUDS							

FROM:

LOSSER, MIKE
HICKORY LANES MOBILE PK.
RT 1 - LOT 62
KAUKAUNA WI 54130

SHIP TO:

LOSSER, MIKE
HICKORY LANES MOBILE PK.
RT 1 - LOT 62
KAUKAUNA WI 54130

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Don't shoot when trigger is pulled all the time. Set it down and it goes off."

MAIN FAULT
Cannot duplicate complaint. However, firing pin fall is slow, because trigger assembly is contaminated with sticky residue - rear safety cam is sticking to trigger assembly side plates - rifle not properly maintained. Trigger pull 3 1/2 pounds, rear lift .0085". Factory sealant has been removed from all adjustment screws.

Send quotation for new trigger assembly at 1/2 normal price, as gesture of good will.
10/24/90
Rifle 11 years old
JLS

REPAIRMAN <i>JLS</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 03085