

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

August 25, 1986

Ms. Pam Marburger
1509 Lexington
Taylor, TX 76574

Dear Ms. Marburger:

Your letter of August 05, 1986 that was addressed to our Wilmington, Delaware facility, regarding the accidental discharge your father experienced while unloading your Model 700, 243 Win. caliber rifle, serial #6433273, has been forwarded to this office for handling.

The recall that Remington made eight (8) years ago was for the Models 600 and 660. The Model 700 has never been recalled.

Generally, the type of problem you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from accidental contact with the trigger when the safety is in the "fire" position.

If you desire, we would gladly examine the rifle to make certain it is in proper operating condition. If you wish, return the rifle via U.P.S. insured to:


REMINGTON ARMS COMPANY, INC.
14 Hoefler Avenue
Ilion, NY 13357
ATTEN: J. A. STEKL

Enclosed for your convenience are two (2) blaze orange stickers to be placed on both outside ends of the package to expedite handling.

Upon receipt, the rifle will be thoroughly examined and, if it is found to be factory faulty, we will make any necessary corrections on a no-charge basis.

Thank you for your letter, and we look forward to the opportunity to be of service to you.

Sincerely,


J. A. Stekl, Supervisor
Product Service

JAS/cal
Enc

PPS 03178