

RECEIVING AND ESTIMATING REPORT

TAL		CUSTOMER ORDER NO.		COMMENTS	
PS	TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE
5/10/91	05/13/91	PI 6-88	A6310434	700 243 WIN	ADL
ACCESSORIES		W/STUDS		ORDER	
				R 91-10741	

FROM:		L/REAR SIGHT		SHIP TO:	
THE MATTHEWS GROUP 709 COUNTRY LANE HOUSTON TX 77024				THE MATTHEWS GROUP 709 COUNTRY LANE HOUSTON TX 77024	

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST: *Fires when bolt is closed. - on chamber and*

IN FAULT: *Cannot duplicate complaint - many attempts were made to duplicate with dummy round in chamber - firing pin did not fall. Trigger assembly contaminated with sticky residue. However, semi-auto gun moves slowly in recovery. Trigger pull 8 pounds, rear lift .009". Rifle could not be made to malfunction.*

RTS: *Offer to clean present trigger assembly, if possible, or we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will if it will better restore confidence in the rifle.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DATE	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6923 REV. 7/90

PPS 03219