

COMMENTS

INITIAL FFS	CUSTOMER ORDER NO.
----------------	--------------------

FROM:

SHIP TO:

MCBRIDES GUN SHOP
C/O NBS
2915 SAN GABRIEL/30TH @N LAMAR
AUSTIN TX 78705

MCBRIDES GUN SHOP
C/O NBS
2915 SAN GABRIEL/30TH @N LAM
AUSTIN TX
78705

CUST NO: 006578 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL	
-------	--

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

AIN FAULT Usable to make up difference, in any way. However, it was noted that rear-hyft cam movement is somewhat sluggish because of lubrication accumulation on trigger assembly, side-plates. Trigger pull $5\frac{1}{2}$ pounds; rear-left .012"

'ARTS

COMMENTS Offer option of run abaining present
tugs assembly if possible. Or, run
tugs assembly with normal cost,
as gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE