

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 26, 1990

McClelland's Gun Shop
1533 Centerville Rd.
Dallas, TX 75228

Dear Sir:

Examination has been completed on the Model 700 BDL 7mm Rem. Mag. caliber rifle, serial number B6220249, that you returned to us a short time ago because, "when safety is pushed the firearm fires."

The returned firearm, which was produced in June of 1980, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to being shipped from our factory.

The general condition of the rifle appeared to be excellent and, in going over the individual parts, we found the headspace, recoil shoulders and chamber all to be normal. Trigger pull was measured to be 4-1/2 pounds and the sear-lift with the safety in the "on-safe" position was also within specifications at .0095".

Examination of the rifle and trigger assembly could not duplicate the malfunction that was reported. Numerous attempts were made to cause the rifle to fire when the safety was moved from the "safe" to the "fire" position, but it did not occur. The only way the rifle could be made to fire was with the safety in the "fire" position and the trigger pulled; it functioned properly and as designed.

Since we found the rifle to function properly in every respect, we are prepared to return it in its present condition. However, if