

**Jim & Shirlene McComb
4802 Precipice Cove
Austin, Texas 78731**

RECEIVED

JAN 08 1985

J. D. GLENN

December 30, 1985

**Firearms Product Manager
Remington Arms Company, Inc.
939 Barnum Ave.
P.O. Box 1939
Bridgeport, Cn. 06601**


**RE: Model 700 BDL
SN # B6561158**

Gentlemen,

On a recent hunting trip the above mentioned rifle discharged when I touched the safety lever. I was examining the stock for what looked like a chip in the slot for the safety, when I pushed the lever it jumped forward and the rifle fired. Luckily the rifle was pointed in a safe direction and no one was hit.

I have talked to several other Model 700 owners and find this problem has occurred with others and I would like to know how I can get the rifle repaired or replaced.

Sincerely,


Jim McComb