

Dear Remington Arms Co,

The enclosed gun (serial no. 134230) has a faulty or worn trigger mechanism. It has been occasionally firing prematurely as the safety is pushed forward or the bolt is lowered to the cocked position.

The last accident occurred in my garage as I worked some handloads through the chamber. one live round went off and I was able to duplicate the premature firing on empty shell cases.

Had I not been practicing good gun safety during these premature firings a serious accident might have resulted.

I am the original owner of this gun which was purchased in 1965 or 66. It
(over)