

TO

Remington Arms Co., Inc.

Arms Serv. Div.

14 Noefler Ave. Ithaca, N.Y. 14850

FROM

MEL'S TRADING POST

105 SO. BROWN
RHINELANDER, WIS. 54501

SUBJECT

XP100 SER. # B7538586 20M BR.

DATE

3/7/94

MESSAGE

Our customer Bill Dinkmeyer - 479-5243
 purchased this gun from us recently and has experienced
 a significant problem. Frequently, when chambering
 a fresh round and closing the bolt the weapon
 fires.

Please repair.

SIGNED

P. Dawson

REPLY

SIGNED

DATE

/ /

EDIFORM 4S 472

AK (50 SETS) 4P 472

SEND PARTS 1 AND 3 INTACT -
PART 3 WILL BE RETURNED WITH REPLY.

carbonless

balance, stock and trigger guard.

have proper shape and tip of trigger
guard cause malfunction.

COMMENTS

Trigger pull 2 1/2 lbs as rec'd

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY RECTOR

DATE

DATE

DATE

DATE

DATE