

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-01047

INITIAL CUSTOMER ORDER NO.

ATTN DENNIS SANITA

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/07/94

01/10/94

BA 1-B0

A6B73380

700 270

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

*Full Scope*MILLER, JOHN
2 MILES HWY 77A
BOX 386
ROBSTOWN

TX 78380

SHIP TO:

MILLER, JOHN
2 MILES HWY 77A
BOX 386
ROBSTOWNTX
78380

CUST NO: 090247 C-B.O.L

ACCOUNT NUMBER

ACCOUNT NUMBER I/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE *25.00*
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
------------------	------	----------	--------	----------	-----	---------

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

*Left May 1980, not subject to call back. Unable to duplicate
function. Found that the action and trigger assembly are covered
with a sticky gunny substance. The bolt stop, hammer and sear safety
are all working properly. Left hammer properly maintained.*

ARTS

COMMENTS

*Replace trigger group assembly
and other action at 12 manual
adjustment cost, as per order of good work.*

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
-----------	-------	-------	------	--------	---------

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE
----------------	------	------	------	------	------

OFFICE COPY

RD5925 REV. 1/92

PPS 03421