

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 93-25432

INITIAL

CUSTOMER ORDER NO.

ATTN: KEVIN CORNELL

EFS

8299

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/24/93

11/24/93

6540891

700 22-250

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

MISCH, DON
RR 1
BOX 26
HUBBARDSVILLE

NY 13355

MISCH, DON
RR 1
BOX 26
HUBBARDSVILLE

NY

13355

CUST NO: 087769 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

DOOR

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Gun purchased used, trigger pull very light, will fire w/out pulling trigger when safety lever is moved to fire

REPAIR CHARGE \$25.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Upon receipt, rifle inoperative. Examination revealed, trigger adjustment screws had been tampered w/ outside of the factory. Original, clear factory sealant had been replaced w/ a red colored, unknown substance. Action needs to be cleaned

PARTS

COMMENTS

Replace complete trigger assembly & clean action, at 1/2 retail replacement cost, as a gesture of goodwill
Go ahead per phone

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

1/92

PPS 03442