

CLONK VALLEY
WELLS, NEWHAM 89735

E. F. SIENKIEWICZ

NOV 9 1978

RECEIVED

11-5-78

DEAR SIR,

IN Aug. OF THIS YEAR I PURCHASED A NEW
REM. 300 MAG. MODEL 700 BDL SEMI-AUT. 96579703.
I INSTALLED A NEW ACCU TRAC REDFILL SCOPE.

I SHOT TWO BOXES OF SHELLS AND WAS VERY
HAPPY WITH THE ACCURACY & WORKMANSHIP OF THE
RIFLE & SCOPE.

A FEW WEEKS AGO I WAS STANDING ON AN
OUTCROPPING OF ROCKS, I PUSHED THE SARY FROM
SAFE TO FIRE AND THE GUN WENT OFF, BEING
CAUGHT OFF BALANCE I WAS KNOCKED OFF OF
THE ROCKS INTO SOME BARBED WIRE. I PULLED
THE MUSCLES IN MY BACK, I LOST 4 WEEKS
WORK BECAUSE OF IT BUT THANK GOD NO ONE
WAS KILLED.

MY RIFLE & SCOPE WERE BADLY SCUTTERED.
THERE IS SOMETHING DANGEROUSLY WRONG WITH THIS
GUN. I FEEL IT SHOULD BE REPLACED ALONG WITH
THE SCOPE. I ALSO SHOULD BE REIMBURSED FOR
LOST WAGES.

I DON'T WANT TO SUE A LAW SUIT OVER
THIS, BUT I WILL IF THIS IS NOT TAKEN CARE
OF IMMEDIATELY.

I HAVE BEEN HUNTING & HANDLING GUNS FOR
30 YRS. I WAS AN EXPERT MARKSMAN IN THE ARMY,
AND I KNOW WHAT I'M DOING. THIS IS THE FIRST
TIME ANYTHING LIKE THIS HAS HAPPENED TO
ME AND IT'S VERY FRIGHTENING.