

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 06/26/92
ENTER REPAIR NUMBER -----> 9211322 15 39 41
7502256 MODEL: XP100
FROM: (CUST NUM: 000093) MTVIEWSPOR GA/CAL: 223 REM
MT VIEW SPTS CTR INC TYPE: FIREBALL
3838 OLD SEWARD HWY ACCESSORIES: SOFT CASE
ANCHORAGE AK 99503 SCOPE MNTS
SHIPPED TO: SCOPE BASE

DATE CODES: WU 8-71
OTHER ACCESSORIES:

COMMENTS: W/LEUPOLD M8-2X SCOPE
W/STUD & SWIVEL

DATES:		TO		FROM		
RECEIVED	05 01 92	GALLERY	00 00 00	00 00 00		ENTERED BY: FPS
OPENED	05 11 92	PROD SERV	00 00 00	00 00 00		REPAIRMAN: HB
ESTIMATED	06 01 92	TAG GUNS	00 00			TYPIST:
PROMISED	00 00 00	REJECTED	00 00			CORRESPONDENT:
REPAIRED	00 00 00	CASH RECEIVED:\$	0.00	BILL TYPE: N		
SHIPPED	06 02 92					

BILL TYPE N/C PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9211322 NO CHARGE EST/LETTER LSTD 06/26/92
CUSTOMER NAME: MT VIEW SPTS CTR INC 15 39 50

=====

REQUEST: GUN ACCIDENTLY DISCHARGED - SEE LETTER
MAIN FAULT: XP100 RECALL DONE-CHAMBER ALTERED OUT SIDE FACTORY
REPAIR TRIGGER UP DATE ONLY-BENCH TEST ONLY
PARTS: \$ 0.00 1 26790 SEAR HOUSING ASSEMBLY

REPAIRMAN'S INITS: HB NUM OF WKS: 03 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 0.00 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR