

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 02095
OUTSIDE WORK: SCOPE MOUNTED DATE: 1-24-71
FROM: NAGEL'S GUN SHOP
FIRE AMMO TYPE: _____ SAN ANTONIO, TEXAS.
& CONDITION: _____ GUN #: 6206774
ASSEMBLER 12 PROOF: R.E.P. INSP.: 9 TEST: 13 CODE: BS = 1/69
HEADING: O.K. GA./CAL.: 270 WIN.
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: "FIRES WHEN YOU RELEASE SAFETY"

INCIDENT: FOLLOWS DOWN

COMMENTS: TRIGGER CLEARANCE ON TRIGGER CONNECTOR = 1.091
MODEL DRAWING = 1.080
1.063 OVERSIZE .008; CONNECTOR
CLEARANCE ON TRIGGER = 1.068 MODEL DRAWING = 1.076
1.079
UNDERSIZE .008. ALTHOUGH THE MALFUNCTION COULD
NOT BE DUPLICATED, THE EXCESSIVE CLEARANCE BETWEEN
CONNECTOR & TRIGGER WOULD ALLOW INTERFER-
ANCE BETWEEN CONNECTOR & SEAR AND RESULT
IN FOLLOW DOWN.