

Copy

15 Oakdale Manor
Suffern, New York 10901
January 18, 1989

Remington Arms Co., Inc.
Ilion, New York 13357

RE: 6mm Remington
Serial #: 97832

Gentlemen:

Several years ago I was notified that the rifle I own may have a defect and should be returned to your factory. The problem was that when operating the bolt, the rifle would sometimes not cock or else the rifle would discharge without touching the trigger. As this was a number of years ago, I do not recall the exact details of this problem.

In any event, this rifle has not been used or fired since it was returned from your factory for repair. Before I sent the rifle back to you, I was not experiencing this problem. But, in the process of cleaning out my closet last week, I picked up the rifle and operated the bolt. Sure enough the first time I tried it it cocked and the firing pin went forward all in the same motion. I am afraid this is what the problem was supposed to be years ago. I am also concerned that the pin could go forward with enough momentum to set the shell off without pulling the trigger.

Please advise me what I should do. Could it be possible that because I wasn't experiencing the problem years ago when it was sent to you that the defect was overlooked?

As I mentioned before, the rifle has not been shot since that time. So nothing should be worn to cause the defect. After repeated operations of the bolt things worked as they should.

Thank you for your attention to this matter.

Sincerely,

Harold Ollweiler
Harold Ollweiler