


THE PALMOUR GROUP


November 10, 1993

file

Remington Arms Company, Inc.
Product Service
14 Hoefler Avenue
Ilion N. Y. 13357



HAROLD H. PALMOUR
DORTHA M. PALMOUR



Attention Mr. Sonita

Dear Mr. Sonita,

Re my telephone conversation of November 9, 1993, concerning my Model 700 rifle.

The problem is it will fire when chambering a round or when a safety is pushed forward.

I shipped it to your attention by U.P.S. today and you should receive it Friday, November 12, 1993, or Monday, November 15.

Please advise what caused the problem and what you can do to fix it. We are very fortunate no one was injured because of this malfunction.

Sincerely,

Harold Palmour

Harold Palmour

1 Copy - File

~~ROUTE 8 BOX 428~~ 4565 FM 3126
LIVINGSTON, TX 77351-9104

(409) 566-4033 OR (409) 967-8885
MOBIL PHONE (409) 327-0861

PPS 03774