

bcc: Bill Ericson

**Remington.**



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

**ILION, NEW YORK 13357**

TELEPHONE (315) 894-9961

May 4, 1989

Mr. Ben H. Parson, Jr.  
7209 East 112th  
Kansas City, MO 64134

Dear Mr. Parson:

Your letter of April 8, 1989, that was addressed to our Bridgeport, CT facility, regarding the accidental discharge of your Remington Model 700 BDL 30-06 caliber rifle, serial number 6747655, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the nature you described.

Generally, the type of problem you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger when the safety was in the "fire" position.

Please, at your convenience, return the rifle via UPS, transportation C.O.D., to:

Remington Arms Co., Inc.  
Attn: J.A. Stekl, Specialist  
Product Service  
14 Hoefler Ave.  
Ilion, NY 13357

Be sure to mark the two (2) ends of the outside of the package "STEKL" to expedite handling.

Upon receipt, the rifle will be thoroughly examined for proper

PPS 03801