

*Remington.*



## REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

April 15, 1986

Mr. Frank S. Peabody  
5424 W. Northview Avenue  
Glendale, AZ 85301

Dear Mr. Peabody:

Your letter of April 01, 1986 that was addressed to our Bridgeport, CT. facility, regarding the safety operation of your new Model 700 300 Win. Mag. caliber rifle, serial number B6317056, has been forwarded to this office for response.

All Model 700 rifles produced after 1981 do not have the "bolt-lock" feature, i.e. - the Bolts can be raised with the safety in the "on-safe" position. Older Model 700 rifles do lock the bolt with the safety on.

The bolt-lock was eliminated based on the results of an independent Marketing survey in which a greater percentage of the shooters felt it was not a necessary feature and preferred the capability of opening the bolt with the safety on.

If you do desire the bolt-lock feature on your new rifle, we can install the necessary parts at a charge of \$15.00 to cover parts, installation and testing. If you are interested, please send your rifle via insured U.P.S. to:

REMINGTON ARMS COMPANY, INC.  
14 Hoefler Avenue  
Ilion, NY 13357  
ATTEN: J. A. STEKL, SUPERVISOR  
PRODUCT SERVICE

In addition, please print "STEKL" on both ends of the shipping box in bold letters.

Thank you for your interest in Remington products and for affording us this opportunity to be of service to you.

Sincerely,

*J. A. Stekl*  
J. A. Stekl, Supervisor  
Product Service

JAS/cal

PPS 03854