

March 1, 1989

Remington Arms Company
14 Hoetler Avenue
Ilion, New York 13357

c/o Arms Division

Re: Remington Model 700
30-06 Rifle
Serial #A6409076

Gentlemen:


I am sending the enclosed 30-06 Rifle to you for repair. Local gunsmiths in Salt Lake City are unable to make the necessary repair.

When the safety is moved from "on position" to "fire position" the rifle fires or discharges, without pulling the trigger. This happens only occasionally and generally after the safety has been in the "on position" for a while.

The rifle has "accidentally fired" twice during hunting trips, almost killing someone each time.

Please advise me at the address below of repair charges and I will remit as soon as possible.

Sincerely,



Duane M. Peterson
7107 South 400 West, #1
Midvale, Utah 84047
(801) 255-3503

DMP/jh