

## RECEIVING AND ESTIMATING REPORT ✓

INITIAL FJB		CUSTOMER ORDER NO.		COMMENTS L/ SIGHTS W/ WILLIAMS SIGHTS	
DATE RECEIVED 10/29/90	DATE OPENED 10/31/90	DATE CODE EN 10-66	SERIAL NUMBER 243174	MODEL AND GRADE 700 30-06 ADL	ORDER R 90-2854
ACCESSORIES					
FROM: <i>W/ RECOIL PAD</i>					
PUVEL, ROBERT H. 35 CLARK DR BRADFORD PA 16701			SHIP TO: PUVEL, ROBERT H. 35 CLARK DR BRADFORD PA 16701		
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		PROM. DATE ESTIMATED VIA V42984304	
REPAIR CHARGE		TAX		INSURANCE	
UPS		PARCEL POST		TOTAL	
GUN CONDITION: <input type="checkbox"/> NEW <input checked="" type="checkbox"/> SLIGHTLY WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> MISUSED <input type="checkbox"/> MARRED					
CUSTOMER'S REQUEST "I pushed the safe to the fire position to empty the gun at that time it fired."					
MAIN FAULT Trigger assembly has been completely misadjusted out of factory (bedout firing from all 3 adjustment screws) No reaction spring fire at all - as described, firing pin would not cock - too little bear engagement coupled with no trigger activation					
PARTS					
Owner claims gun is just over 2 years old, however, it was produced in October of 1966.					
Send repair quotation for new trigger assembly.					
REPAIRMAN BFA		PROOF		CLEAN	
GALLERY TESTER		DATE		TARGET	
DATE		DATE		DATE	

OFFICE COPY

RD6925 REV. 7/9

PPS 03999