Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

August 31, 1990

Red's Gunsmithing 1230 East 68th Ave. Suite 102 Anchorage, AK 99518

Dear Red:

Examination has been completed on the Model 700 Classic .300 H&H Magnum caliber rifle, serial number B6463765, that you returned to us for Bob Rehm of the "Gun Nutt" because the "striker can be released with the safety on, ala expert's test in Campbell vs Rem. in Alaska." I know from our later telephone conversation that Mr. Rehm's concern was that the rifle could be fired through a manipulation that involved pulling and pushing up on the trigger connector with a tool, and that the reported firing with the safety "on" was a handwriting error.

The returned firearm, which was produced in April 198° has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection markings, which indicates that it successfully passed all of the necessary tests and inspections before leaving the factory.

The general condition of the rifle was excellent. In going over all of the individual parts, we found the headspace, recoil shoulders and chamber to be normal.

Function testing of the rifle was normal. Trigger pull was measured to be 5-1/4 pounds and the sear lift with the safety in the "on-safe" position was within specifications at .008".

Although the rifle did function properly when in a normal manner consistent with use in the field, I did observe that the rifle