

**Remington.**



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 30, 1991

Mr. Joe Reese  
2695 W 5th Street  
Yuma, AZ 85364

Dear Mr. Reese:

This is in reply to your December letter, accompanied by a Model 700 trigger assembly, in which you requested five (5) Owner's Manuals and a repair quotation for the trigger assembly.

Subject four (4) Model 700 and one (1) Model 742 Owner's Manuals are being sent to you at no charge under separate cover. We trust they will complement the associated rifles.

Please note the red warning notice on page five (5) of the enclosed Model 700 Owner's Manual which states not to adjust the trigger assembly. To do so effectively voids that part's warranty. Relatedly, your returned trigger assembly has been adjusted outside the factory. Therefore, in order to return to you a functionally, safe and operational trigger assembly, we'd have to charge you for it. Per your letter, we infer that a \$30.00 plus charge will be prohibitive to you so we're scrapping the returned assembly in lieu of charging you for a new replacement fire control.

However, we do want to be as helpful to you as possible in this regard. Therefore, we ask that you retain this letter for possible future reference in case you do at some point require a replacement trigger assembly for one of your four Model 700 rifles. If that time comes, please send me your request, along with a copy of this letter, and we'll apply a special price to you for factory or Remington Recommended gunsmith installation of a new trigger assembly.