Dec. 10, 1990

Remington Arms Inc Arms Service Division 14 Hoefler Ave. Ilon N.Y. 13357

and the construction of the approximation of the second state of the second second second second second second

Attention: TARP Department

Please find enclosed my Remington 308, model 660, serial number 6209651. Just to give you a little history on the rifle, my brother purchased the gun new in Detroit Mich. about 1970. I have been the owner since 1974. Over the years the rifle had discharged about three time when the safety was released. I had always thought that maybe it was due to my error until last week. I had just returned to camp after a day of deer hunting, carefully released the safety when (BOOM) the rifle discharged and the bullet went into my pickup truck. (Did you ever see the damage a 308 can do to a pickup truck?). I can finally laugh about this and be thankful that I shot my truck and not one of my hunting partners. I understand from talking with Customer Service at Remington that this model 308 was recalled for the same problem that I am having. Please repair the rifle and return to me. Please take good care of my 308, its my favorite rifle,I taken 12 deer with it over the years.

Thank Your Very Much

Ralph & Reynolds Ralph G. Reynolds Route #1 box 460 Ridgewood Hgts Caryville Tenn. 37714