

# RECEIVING AND ESTIMATING REPORT ✓

INITIAL PPS		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 03/18/91	DATE OPENED 03/20/91	DATE CODE AA 3-B0	SERIAL NUMBER A688790B	MODEL AND GRADE 700 30-06 LH BDL		ORDER R 91-0760	
ACCESSORIES W/STUDS		L/SIGHTS					

FROM:	SHIP TO:
ROBESON, JIM 785 GARNER LANDER WY 82520	ROBESON, JIM 785 GARNER LANDER WY 82520

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA V42249531
----------------	--------------------	--------------------------------	------------	------------	-----------	------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☒ MARRED

CUSTOMER'S REQUEST "see it will fire at target by moving the safety off to fire without engaging the trigger."

MAIN FAULT Cannot duplicate complaint, however, (1) trigger assembly is contaminated with excessive oil & dust (2) trigger assembly has been improperly adjusted outside factory, as evidenced by foreign bullet small & round (3) trigger pull below spec at 2 pounds (4) insufficient over-travel (5) insufficient rear engagement. Rifle has not been properly maintained.

PARTS

Send quotation for new trigger assembly at 1/2 normal cost as gesture of good-will.

Warn against outside "tinkering" with trigger assembly adjustments.

REPAIRMAN JTB	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE