

RECEIVING AND ESTIMATING REPORT

COMMENTS

Stekl

ORDER
R92-16016INITIAL
FPS

CUSTOMER ORDER NO.

DATE RECEIVED

07/31/92

DATE OPENED

08/11/92

DATE CODE

RX 11-73

SERIAL NUMBER

6685506

NEW SERIAL NUMBER

MODEL AND GRADE

700 7MM MAG

LH BDL

ACCESSORIES

W/STUDS

L/SIGHTS

FROM:

ROPER, JOHN
2284 CODY ESTEY RD
RHODES

MI 48652

SHIP TO:

ROPER, JOHN
2284 CODY ESTEY RD
RHODESMI
48652

CUST NO: 064663 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER NO.

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

8-19-92

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	Clean will fire by moving back					E1
BOLT ASSY.					E2	F2
BARREL ASSY.				D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

As required, trigger assembly is imperative. Trigger assembly is contaminated with gunning residue, clean sight can and other additional trigger parts are sticking to trigger assembly and plate are not moving. This condition appears to have resulted from improper maintenance. Customer has all adjustments out of specification.

PARTS

COMMENTS

Offer new trigger assembly at normal cost as portion of good as same customer has mis-identified present trigger assembly.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATE

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

R92025 REV. 1