

REPAIR GUN INQUIRY FUNCTION: E (N)EXT (P)REV (I)NQ (E)XACT 05/10/93  
9225724 11 36 42

ENTER SERIAL NUMBER -----> A6564027  
FROM: SCHMIDT

SCHMIDT, PATRICK A  
3241 JACKS RUN RD

MODEL: 700  
GA/CAL: 270  
TYPE: BDL  
ACCESSORIES: SLING STRAP  
W/STUDS  
W/SWIVELS

WHITE OAK PA 15131  
SHIPPED TO:

DATE CODES: LQ 2-78  
OTHER ACCESSORIES:

COMMENTS:

DATES:		TO	FROM	
RECEIVED	11 23 92	GALLERY	12 30 92	12 31 92 ENTERED BY: JJM
OPENED	12 01 92	PROD SERV	00 00 00	00 00 00 REPAIRMAN: BW
ESTIMATED	00 00 00	TAG GUNS	00 00	00 00 00 TYPIST:
PROMISED	00 00 00	REJECTED	00 00	00 00 00 CORRESPONDENT:
REPAIRED	00 00 00			
SHIPPED	01 12 93			
BILL TYPE COD				

PF1 = VIEW DETAIL  
PF4 = SERIAL NUMBER BROWSE

REPAIR NUMBER: 9225724 CHARGE (AWAIT RESP) COD PRINTED 05/10/93  
CUSTOMER NAME: SCHMIDT, PATRICK A 11 37 16

=====

REQUEST: "HESITATION WHEN FIRST SHOT FIRED"

MAIN FAULT: COULD NOT DUPLICATE CONDITION CUSTOMER DESCRIBED. HOWEVER  
DISASSEMBLY OF RIFLE REVEALED THAT A GUMMY SUBSTANCE WAS  
FOUND ON THE TRIGGER ASSEMBLY, AND BOLT STOP. CLEANING RE-  
QUIRED. TRIGGER PUL 5 1/2 LBS.- SEAR-LIFT .007

DATE OF MFG: 02-78

PARTS: \$ 30.00 1 26345 TRIGGER ASSEM RH

LABOR: \$ 0.00 BASED ON STICKY/GUMMY CONDITION OF TRIG ASSEM., REPLACE

\$ 0.00 TRIG ASSEM. AT 1/2 NORMAL COST, AS GESTURE OF GOOD-WILL

\$ 0.00 CUSTOMER HAS AUTHORIZED REPAIR UNDER \$50.00 -

\$ 0.00 APPROVED 12/29/92 PER PHONE

\$ 0.00 CLEAN - TEST

\$ 0.00 BW/HAR

REPAIRMAN'S INITS: BW NUM OF WKS: 00 CORRESPONDENT'S INITS:  
TOTAL VALUE:\$ 39.80 PF1 = INQ PF2 = ESTIMATE  
NO MORE DATA AVAILABLE FOR THIS REPAIR