

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

July 30, 1992

Mr. Larry Spangler
P.O. Box 580
Chino Valley, AZ 86323

Dear Mr. Spangler:

Examination has been completed on your Model 700 ADL, serial number 86223879, which you returned for alleged accidental firing.

Numerous attempts were made with and without dummy ammunition, and your incident could not be duplicated. The only way the rifle could be made to fire was with the safety in the off position and the trigger being pulled.

We also removed the barreled action from the stock to more closely analyze the trigger assembly and found all parts correct in location and specification. However, we did find that the entire trigger assembly was very heavily oiled. Under certain colder weather conditions, too much lubricant can interfere with the trigger assembly parts and inhibit their proper operation.

As we feel that your trigger assembly, properly delubricated, is a safe one, we are prepared to return your rifle with its properly delubricated original trigger assembly. We also are prepared to offer you an installed new trigger assembly at a special half price of \$24.55 plus an state tax and \$5.00 shipping. An estimate is being sent to you for the latter option.

Of course, you also have the final option of requesting that your rifle be returned as received. No work has been performed to-date.

Please refer to R#92-11339 in any correspondence.