

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

Mr. Paul R. Stafford
9401 Fireside Drive
Shreveport, La 71118

January 26, 1987

Dear Mr. Stafford:

Your letter of January 6, 1987 that was addressed to the Firearms Product Manager, Bridgeport, Ct., regarding the accidental firing your father experienced with your Model 700 ADL 270 Win caliber rifle, serial number 86735637, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the nature you described, and that your father was injured as a result of the occurrence.

Generally, the type of problem you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger when the safety was in the "fire" position.

Please, at your convenience, return the rifle via U.P.S., transportation C.O.D. to:


Remington Arms Co., Inc.
Attn: J. A. Stekl, Supervisor
Product Service
14 Hoefler Avenue
Ilion, N.Y. 13357

Be sure to mark the two (2) ends of the outside of the package "STEKL" to expedite handling.

Upon receipt, the rifle will be thoroughly examined and, if it is found to be factory faulty, we will make any necessary corrections on a no-charge basis.

Thank you for bringing this matter to our attention and for having afforded us this opportunity to be of assistance to you.

Sincerely,


J. A. Stekl, Supervisor
Product Service

JAS:cm

PPS 04806