

REMINGTON ARMS, INC.
SPECIAL SERVICES DEPT.
PERSONAL ATTENTION:**JANET KIPPER**
14 HOEFLER AVENUE
ILION, NEW YORK 13357

STAFFORD SUPPLY, CO.
7600-A FULLERTON ROAD
SPRINGFIELD, VA. 22153
(703) 222-5151

JULY 31, 1990

DEAR JANET,

PER DISCUSSION TODAY BETWEEN MYSELF, AND MR. ROGER POTTER, ENCLOSED PLEASE FIND AN XP-100, SN:B7522755, 7mmBR. THIS XP-100 IS BRAND NEW, HAS NEVER BEEN SOLD OR DELIVERED TO A CUSTOMER AND ONLY HAS BEEN EXAMINED AND TEST FIRED BY MYSELF AND ANOTHER TECHNICIAN WHO WORKS FOR US.

AS I OUTLINED TO ROGER DURING OUR CONVERSATION, THERE ARE SEVERAL PROBLEMS WITH THIS XP-100. ROGER REQUESTED THAT IN THIS MEMO I MENTION THAT HE WISHED YOU TO PERSONALLY HANDLE THIS PROBLEM, AND SEE THAT THIS XP-100 WAS DELIVERED DIRECTLY AND PERSONALLY TO MR. HERB BROWN, OR MR. TOM NAGLE, OF THE XP GUNSHOP.

THE MOST SIGNIFICANT PROBLEM BECAME OBVIOUS WHEN WE MOUNTED SIGHTS ON IT, AND IT SHOT FIFTEEN INCHES (15") TO THE RIGHT AT 50 YARDS. IT WAS IMPOSSIBLE TO CORRECT POINT OF IMPACT TO POINT OF AIM. UPON CLOSE INSPECTION, IT APPEARS THE BARREL IS WARPED. THE OTHER PROBLEMS ARE OUTLINED BELOW:


A: ONE OF THE TWO TRIGGER ASSEMBLY MOUNTING SCREWS IS BROKEN. IT HAS BEEN REPLACED, IN PLACE, AS IT WAS WHEN WE DISASSEMBLED THE WEAPON.

B: THE STOCK IS CRACKED (SPLIT) AT THE FRONT MOUNTING SCREW. NOTICE THE ARROWS WHICH INDICATE AREA OF DEFECT.

C: THERE WAS NO SOFT NYLON WASHER IN PLACE (AS IS SPECIFIED) AT THE FRONT MOUNTING SCREW.

AS YOU CAN SEE, THIS XP-100 HAS NOT BEEN SUBJECT TO ANY ABUSE. WHAT YOU SEE IS WHAT CAME FROM THE FACTORY. WE FEEL THAT POSSIBLY THE BEST WAY TO SATISFY OUR COMPANY, AND ULTIMATELY THE CUSTOMER WHO WILL BE USING THE XP-100 TO HUNT WITH AND SHOOT IN SILHOUETTE COMPETITION WITH, WOULD BE, AS ROGER SUGGESTED TO REPLACE THIS XP-100 WITH A NEW WEAPON. PLEASE LET ME KNOW WHAT YOU THINK.

BEST REGARDS,
STAFFORD SUPPLY CO.


DAN SCOTT