


The safety of the Model 700 rifle is designed in such a way that when it is in the "on-safe" position, an internal arm lifts the trigger sear and safety cam to block the firing pin head, so the firing pin cannot reach a cartridge in the chamber to fire it. The only way this system can fail, is if a part or parts is broken. This was not found to be the case.

Since we found the firearm to function normally in every respect, we are prepared to return it to you in its present condition. However, if you desire, we will install a new trigger assembly at no-charge, as a gesture of good-will, if it will restore your confidence in the rifle. We will await your decision and reply.

Thank you for affording us the opportunity to examine your rifle and report our findings.

Sincerely,



J.A. Stekl, Specialist
Product Service

JAS:tp

Remington Arms Company, Inc.

PPS 04856