

RECEIVING AND ESTIMATING REPORT ORDER 94-12134

INITIALS: CUSTOMER ORDER NO.

DATE RECEIVED: 04/06/94 DATE OPENED: 04/06/94 DATE CODE: AA 3-B0 SERIAL NUMBER: A6879484 NEW SERIAL NUMBER: MODEL AND GRADE: 700 30-06 ADL

ACCESSORIES:

FROM: STEVENS WHOLESALE INC
7023 US 60
ASHLAND KY 41101 SHIP TO:
STEVENS WHOLESALE INC
7023 US 60
ASHLAND KY 41101

CUST NO: 021584 C.O.D.

ACCOUNT NUMBER: ACCOUNT NUMBER INC: WRITE ☐ FROM DATE: ESTIMATED: VIA: UPS

GUN CONDITION:

☐ NEW

☐ LIGHTLY WORN

☒ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

Product Service

REPAIR CHARGE: 20.00

EXCISE:

TAX:

INSURANCE:

UPS:

PARCEL POST:

TOTAL:

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5			E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: *We could not duplicate the Customer Concern. Removal of the trigger assembly would be required and trigger assembly can be used in many instances. The trigger adjustment screws have been set to the point that the trigger (adjustable) trigger and follow over main press.*

PARTS: *Trigger Pin - 1/4" dia*

COMMENTS: *Replaced trigger assembly and then action at 1/2" main adjustment. Cost in getting it good was \$20.00*

REPAIRMAN: *C.C.* PROOF: CLEAN: TEST: TARGET: PATTERN:

GALLERY TESTER: DATE: DATE: DATE: DATE: DATE:

to A/S 5/19/94