

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 17, 1989

T & D Sporting
Attn: Mr. Terry Bishop
Historic 7A
Bennington, VT 05201

Dear Mr. Bishop:

Examination has been completed on the Model 700 BDL 270 Win caliber rifle, serial number B6207480, that you returned to us a short time ago because "...rifle fired when pushing the safety off...".

The returned firearm, which was produced in May of 1980, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to being shipped from our factory.

The general condition of the gun appeared to be very good. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the malfunction that was reported. Many attempts were made to cause the rifle to fire upon moving the safety to the "fire" position without success. Factory seals were intact on the trigger adjusting screws, indicating that no adjustment had been made to the trigger outside our factory. Trigger pull measured 5-1/2 pounds, and sear lift with the safety in the "on-safe" position was well within specifications at .008". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.

Hold to reply
R 88-34929
cc: Bill Ericson