

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL CUSTOMER ORDER NO.

LCS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
11/30/90	12/05/90	BC 1-82	B6370339	700 243 HDL	R 90-3163

ACCESSORIES SLING STRAP W/STUDS W/SWIVELS SCOPE BASE

FROM: WARNER, ROGER
4504 STYPES BRANCH RD
SALEM VA 24153

SHIP TO: WARNER, ROGER
4504 STYPES BRANCH RD
SALEM VA 24153

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	---------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *fixes on bolt closing*

MAIN FAULT *Trigger assembly is contaminated with heavy, gummy residue. Internal trigger parts not able to move freely. Semi-safety cam and trigger and connector sticking to side plate of trigger assembly. Improperly maintained!*

PARTS *Send quotation to clean present trigger assembly, if possible. If not send quotation for replacement assembly at $\pm$ normal cost, as a gesture of good-will*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 05343