

cc: D.J. Sanita

**Remington.**



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 5, 1985

Mr. Gerald W. Wayne  
RR #1, Box 111  
Goodridge, Minnesota 56725

Dear Mr. Wayne:

This is in reply to your letter of November 9, 1984, and please accept our apologies for the tardy answer.

We certainly regret you had an accidental firing problem with your Model 700 in 25-06 Remington caliber. However, the Remington Model 700 has had the same trigger assembly and performed satisfactory for twenty three years. Generally, accidental firing results from improper maintenance of the rifle, improper adjustment of the trigger assembly outside of the factory or inadvertent contact with the trigger as the safety is released.

As we certainly do not want you to own a Remington rifle you don't trust, as a gesture of good-will we will, at no charge, replace your current trigger assembly with a new style Model 700 trigger assembly. In order to accomplish this work, please send your Model 700 via United Parcel Service transportation C.O.D. to:

Remington Arms Company, Inc.  
Arms Service Div.  
Attn: D.J. Sanita  
Ilion, New York 13357

Please mark both butt ends of the package to Mr. Sanita's attention for fast service.

Again, Mr. Wayne, we certainly regret your experiencing a mishap of this nature and hope our action meets with your approval.