

RECEIVING AND ESTIMATING REPORT

COMMENTS

64

TIAL JM	CUSTOMER ORDER NO.		DATE RECEIVED 4/19/91		DATE OPENED 04/23/91	DATE CODE EV 10-79	SERIAL NUMBER A6814285	MODEL AND GRADE 700 30-06 BDL	ORDER 91-09592
ACCESSORIES SLING STRAP W/STUDS		W/SWIVELS		SOFT CASE		SCOPE BASE			

FROM:	SHIP TO:
WELDON, H W 10701 EDGEWATER RD FORT SMITH AR 72903	WELDON, H W 10701 EDGEWATER RD FORT SMITH AR 72903

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED 5-7-91	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	---------------------	------------

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *Repair - and letter of explanation*
explanation - claims firearm discharged on
safe release twice

N FAULT: *Sent to J. Stekl*
cannot duplicate complaint - rifle cannot be made to fire when safety is
disengaged. However, disassembly of rifle revealed trigger assembly is shipping wet
with oil. This condition coupled with cold temperatures could cause problems
in lift - 0.12"; trigger pull 4.5 pounds.

Offer to clean present assembly (if possible).
If not, offer replacement trigger at
minimal cost, as gesture of good-will.

REPAIRMAN 64	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 05380