

R94-13828

SEALANT
IS
MISSING

{ Trig pull has been adjusted to
2 1/2 - 3 lbs.

{ On-tilt screw has been re-set.

Star engagement screw - OK

Star lift .006

Check w/ attribute gage in A/S -
(baseline w/ ours)